<b>S</b> SIR	SIRAYA Tech		Dry prints	completely before of	curing! Use H	airdryer to speed	up the process. Do	not cure und	ler sun with a w	et print!	
ser Gui	de for Build		For other resi	n user guides, please visit h	ttps://siraya.tech.s	upport section					
11 d 1 <b>6</b> d -	ble control of the	and the state of the state of		to to the state of the between the total		a salata					
	ance between hardne			ints that require high precision	i, no warping and ta	ppable					
is an a good ba	under between narane	so, resolution and	a bit liexible to make	it lacar for projects.							
e recommend	you print Build over	20 C									
Please	downloa	d profi	les base	e for Elegoo	. Anvcu	bic. Phroz	en. Peopol	v. EPAX.	Creality		
		_		p4L9mKYebY90lfHHC				<b>,</b> ,	, <u>-</u>		
.tpo.//dilve.	googic.com/anv	<u> </u>	ZT_GOOTT JIDE	<u> </u>	J. dop Gridning						
est print with r	ecommended suppor	t setting, see bel	ow								
xposure											
ecommended		Resin Tempertu	re 25-35C		Room temperature 20-25C						
rinter	Layer Height	Exposure (s)	# of Initial Laye		Exposure (s)	# of Initial Layers	Exposure for Init Layers	Note			
hoton	50um	12 (s)	4	60 s	12(s)	6	60 s				
eopoly Phenom	50um	13.5s	6	65 s	13.5s	6	65 s	see below for de	etail settings		
PA X1	50um	9.5 (s)	4	50 s	9.5 (s)	4	50 s				
PA X1	100um	12 (s)	4	75 s	12 (s)	6	90 s				
huffle huffle XL	50um 50um				7.5(s) 11(s)	5	60 s 75 s				
hrozen Transfor					8(s)	5	60 s	*see additional i	nfo below		
7	50um				8(s)	5	60 s				
nkspire	50um				11 (s)	6	75 s	Inkspire does no	ot specify its light output	, one user told us it is	very clos
hoton S	50um	9.5s	5	65s	9.5s	5	65s				
lars	50um	9.5 (s)	4	50 s	9.5 (s)	4	50 s				
ars Pro	50um	6.5s	4	40s	6.5s	4	40s				
1 noton Mono	50um Where to find printer	orofiles: https://dri	10	40 s //folders/1eCz4_dc0fT-jfBLp4L	7s 9mKYehY90lfHHO2	10	45 s				
hoton Mono X				/folders/1eCz4_dc0fT-jfBLp4L							
ars 2 Pro				/folders/1eCz4_dc0fT-jfBLp4L							
ars 3				/folders/1eCz4_dc0fT-jfBLp4L							
aturn				/folders/1eCz4_dc0fT-jfBLp4L							
onic Mini 4K		Where to find printer profiles: https://drive.google.com/drive/folders/1eCz4_dc0fT-jfBLp4L9mKYebY90lfHHO?usp=sharing  Where to find printer profiles: https://drive.google.com/drive/folders/1eCz4_dc0fT-jfBLp4L9mKYebY90lfHHO?usp=sharing									
ight 4K ega 8K				<u>/folders/1eCz4_dc0fT-jfBLp4L</u> /folders/1eCz4_dc0fT-jfBLp4L		<u> </u>					
eopoly Printers				/folders/1eCz4_dc0fT-jfBLp4L							
efore Printing											
s a good praction	ce to stir resin in the va	it and expose the l	bottom of the vat to a	air before printing. This repleni	sh oxygen in the val	t and helps reduce peel fo	rce.				
ecommend bes	t support settings:										
le recommend n	nedium preset support	setting in chitubos	r for smaller prints.	leavy support for large prints o	n large priners						
		•		for each preset and copy them	• .	are of choice					
,				and the second s							
leaning:											

Use a painter brush (or any brush made with hair) remove excess resins on the printed part with Use 95% concentrated Ethanol (preferred) or IPA to clean. Some form of methnol should work but make sure it does not contain acetone.

Do not submerge the	e parts in alcohol for more than	30 seconds. After 2-3 minutes	of cleaning action, remove	alcohol with a hair o	dryer or air blower. For co	mplex part with lots cavities, it	may be a good ide	a to clean/dry mu	Itiple times.		
User can check by to	ouching the dryed surface of the	e part to see if it is still sticky. If	the dryed surface is still s	ticky, wash some mo	re and dry again.						
Post Curing:											
Build reached its opt	timal strength when the printed	part is post-cured with UV after	cleaned. Use 395-405nm	UV light and cure fo	r about 1-2 minutes.						
Make sure resin is co	completely cleaned off and there	e is not alcohol left (it needs to b	e dry) on the print before	curing.							
It is important to dr	ry the print made by Build co	mpletely before post curing. 1	here is no need to use t	ne "submerge in wa	ter" technique. If you d	ecided to do so, make sure d	ry the print as so	on as you are d	one curing using	hot air / dehydr	ator
Mechanical Proper	ties										
Shore Hardness (D) 73D											
Tensile Stress at Break	k (MPa) 33										
IZOD Impact (Notched	ed, J/m) 27										
HDT at 0.455 MPa (°C	C) 68										
Elongation at Break (%	%) 8										
Young's Modulus (MPa) 850											
MSDS											
https://drive.google.com/file/d/Inn_BFdppXtCngaLZTIXL6I7Y8I7Bmmzk/view?usp=sharing											
TDS											
https://drive.google.com/file/d/1BwUNGdiv5DE_r0xTRJs-xlbd2-2avMXO/view?usp=drive_link											