

# FURminator Undercoat deShedding Tool

## What is the best tool to use for my pet?

Check out our **Pet Grooming Solution Center** at <http://www.furminator.com/> to find a recommended grooming regimen for your dog or cat.

## Can the undercoat deShedding tool be used on all pets?

The undercoat deShedding tool may be used on most animals that shed, including dogs, cats, and other pets with an undercoat. The undercoat deShedding tool should not be used on non-shedding breeds or on pets with particularly sensitive skin.

## How often and how long should I use the FURminator undercoat deShedding tool?

For best results, use the FURminator undercoat deShedding tool 1-2 times a week for 10 to 20 minutes each session, though the actual time will vary depending on your pet's breed, the condition of their coat, and the thickness of the pet's individual coat. It may be necessary to use the undercoat deShedding tool more frequently during heavy shedding seasons. FURminator's grooming edge is designed to make grooming pets faster and easier while the Skin Guard design eliminates digging and allows the tool to glide over most pet skin.

## Where should I perform the grooming process?

The undercoat deShedding tool will remove large amounts of loose hair and undercoat, so a location that is easy to clean, such as a tile floor indoors or an outdoor area, makes cleanup more convenient. Most importantly, always choose a location where your pet feels comfortable and safe.

## How do I take care of my undercoat deShedding tool?

- Brush your pet before using the undercoat deShedding tool to remove any mats or tangles. Using the tool on matted or tangled fur can bend or break the teeth, as well as feel uncomfortable for the pet.
- Be careful not to drop or place the undercoat deShedding tool where it can fall, as it may result in damage to the tool's teeth
- The deShedding edge can be cleaned with warm water and a mild soap if necessary. Cleaning can reduce the feeling of a dull edge by reducing dander collection on the teeth of the deShedding edge. Dry the undercoat deShedding tool completely before storing.
- The FURminator undercoat deShedding tool has an Edge Guard around the deShedding edge, so the tool does not require a cap when stored. Simply press down the FURejector® button and pull towards you to lock the Edge Guard into place, protecting the deShedding edge.