

Model: 377DAT – Customer Report: Keys and don't work Properly

Location was verified and no problem has been found as mentioned per notification. Visual and functional inspection was performed as a part of AQL control plan from a total inventory of 3372 pcs



Ship box



Product Packaging



Picture Samples of Product



We have Inspected 3 sets of lock and we haven't found any anomalies, all lock open with their set of keys and no other issues were found