HUANUO

HNDMA119B-DS

QUICK START GUIDE

1-800-556-0533 (US/CA) Mon–Fri, 8am–8pm (CST)
support@huanuo.com www.huanuo.com

Before You Start

Desk Check List
- Wooden desk required
- Desk thickness: 0.59-3.54″ (15-90mm)
- Desk mounting type


Monitor Check List
- Weight capacity: 4.4-19.8 lbs (2-9 kg)
- VESA range: 75×75mm - 100×100mm


1 Before Installation: Confirm Desk Mounting Type

If needed, use a spacer for a better fit on irregular or too-thin desks.

1-1 C-Clamp Mounting










1-2 Grommet Mounting









2 Attach the Lower and Upper Arms





3 Hang the Monitor on the Arm






Use the monitor plate to level the connector, then push up the locking tab to remove it.






4 Tension and Tilt Adjustments

Arm falls down?
Turn clockwise ("+" direction) to raise the monitor.



Arm rises up?
Turn counterclockwise ("-" direction) to lower the monitor.



Monitor is sagging?
Turn clockwise ("+" direction) to hold it more firmly.

