

► SCREW PACKAGE



M6x10(x4)

A




M6x45(x4)

B




(x1)

C




(x1)

D



(x2)


E



(x2)


F

► PARTS INCLUDED



x1

G



x1

H



x1

I



ASSEMBLY INSTRUCTIONS

D-M01





► SCREW PACKAGE



1



2



3



4

