1、确认Host和Device 接口的规格，Host连接cable USB连接器，Device连接cable Type-C连接器

1、Confirming the specifications between source and device, Host connect with cable USB connector and Device connect with cable Type-C connector


Source

Cable

Device

2、Cable两端分别完全插入Host与Device

2、Put cable connector completely inserts Host and Device respectively

OK: contacting completely

OK: contacting completely

NG: contacting partly

NG: contacting partly

3、如果Cable存在不工作的状况，请简易的进行如下检查：

3、 If the cable do not work, Please simply check as follow:

3.1 确认Type-C connector内部是否存在异物或内部Pin针是否存在异常，请清洁干净重新连接

3.1 Please confirm whether there was foreign matter inside type-c connector or any abnormity in the Pin , if yes, please clean it and reconnect

Inside was OK

foreign matter in connector

3.2 进一步检查Source和Device 充电接口内部是否有金属屑/水溶剂等异物，请清洁干净后重新连接

5.2 Further confirm whether there is any metal chip/water solvent or other foreign matter in the source and device charging port? Please clean it and reconnect.