



USB-C POWER METER TESTER

- 1** Remove transparent screen protector.




- 2** Attach the USB-C Tester to a Type-C port of your device.




MEASURE INPUT POWER

- 3** Attach a cable to the USB-C Tester and connect it to a power source.




- 4** Measured Voltage (V), Current (A), and Milliampere-hours (mAh) will be shown on the built-in screen.



MEASURE OUTPUT POWER

- 5** Attach a cable to the USB-C Tester and connect it to a USB-C monitor or hub.



- 6** Measured output Voltage (V), Current (A), and Milliampere-hours (mAh) will be shown on the built-in screen.

