



Troubleshooting

Message

Reason

Solution

"EEEE"

Scale overload.
Maximum weight capacity:
5.000g (176 oz).

Remove the object from the scale to avoid damage.

"Unse"

Calibration error.
Unable to measure weight.

Re-installed the batteries, and then put the scale on a flat surface immediately, keep weight stable when turning on scale.



Battery power is low.

Install new batteries.