

**ATTENTION:** Refer to the appropriate shop manual for your vehicle to obtain specific service procedures for this part. If you do not have a service manual or lack the skill to install this part, it is recommended that you seek the services of a qualified technician. Pay special attention to all cautions and warnings included in the shop manual. Read and follow all instructions carefully. This product is only designed to function properly on specific vehicle applications. Please verify that the vehicle requirements match the product specifications and application notes for this part.

**Cadillac Escalade 2006–2003; Chevrolet Avalanche, Suburban, Tahoe 2006–2003;  
GMC Sierra 2007–2003; GMC Yukon 2006–2003; Chevrolet Silverado 2007–2003;  
Hummer H2 2007–2003; Buick Rainier 2007–2004; Chevrolet Trailblazer 2009–2002;  
GMC Envoy 2009–2002; Oldsmobile Bravada 2004–2002**

**This Climate Control Module will automatically undergo a configuration procedure after installation. DO NOT use an external programmer or scan tool. Follow the procedure below to complete configuration. If unit fails to configure after two attempts, call Technical Support at 866-933-2911.**

### Configuration Instructions

- A. With the new module installed, start the vehicle to begin automatic configuration. Engine must be running for entire process.
- B. Wait while the system performs a configuration sequence. While configuration is in process LED(s) will be lit according to the vehicle application. See Table A below.
  - a. Configuration may take up to one minute
- C. Configuration is complete when all button LEDs turn off.
- D. If configuration is unsuccessful:
  - a. Remove power from the module by unplugging both connectors.
  - b. Wait 15 seconds. Reattach both connectors.
  - c. Repeat the procedure beginning with Step A.
  - d. If configuration is unsuccessful after two attempts, call Technical Support at **866-933-2911**.

**Table A**

<b>Configuration Number</b>	<b>Vehicle Applications</b>	<b>LED Active During Configuration</b>
01	2003–2004 (Cadillac) Escalade, (Chevrolet) Avalanche, Suburban, Tahoe, (GMC) Yukon 2003–2004 (Chevrolet) Silverado, (GMC) Sierra	Rear Defrost (C)
02	2005–2006 (Cadillac) Escalade, (Chevrolet) Avalanche, Suburban, Tahoe, (GMC) Yukon 2005-2007 (Chevrolet) Silverado, (GMC) Sierra	Front Defrost (B)
03	2003–2007 (Hummer) H2	Front and Rear Defrost (B & C)
04	2004 (Buick) Rainier 2003–2004 (Chevrolet) Trailblazer, (GMC) Envoy, (Oldsmobile) Bravada	Recirculation (A)

**Disclaimer:**

Even though every attempt is made to ensure this information is complete and accurate, it is impossible to account for all possible circumstances or situations. Please consult with a qualified auto technician before attempting to perform any work you are not qualified to do. Automobiles can be hazardous to work on; be sure to take all necessary safety precautions. Failure to do so may result in property damage or personal injury. Certain motor vehicle standards and performance requirements may apply to your motor vehicle (such as Federal Motor Vehicle Safety Standards by the National Highway Traffic Safety Administration). Be sure that your work is performed in accordance with such standards and that you do not disable any motor vehicle safety feature.

**ATTENTION:** Refer to the appropriate shop manual for your vehicle to obtain specific service procedures for this part. If you do not have a service manual or lack the skill to install this part, it is recommended that you seek the services of a qualified technician. Pay special attention to all cautions and warnings included in the shop manual. Read and follow all instructions carefully. This product is only designed to function properly on specific vehicle applications. Please verify that the vehicle requirements match the product specifications and application notes for this part.

Table A

Configuration Number	Vehicle Applications	LED Active During Configuration
05	2005–2006 (Buick) Rainier 2005–2006 (Chevrolet) Trailblazer, (GMC) Envoy	Recirculation and Rear Defrost (A & C)
06	2002 (Chevrolet) Trailblazer, (GMC) Envoy 2002 (Oldsmobile) Bravada	Recirculation and Front Defrost (A & B)
07	2007 (Buick) Rainier 2007–2009 (Chevrolet) Trailblazer, (GMC) Envoy	Recirculation, Front and Rear Defrost (A, B, & C)



## Disclaimer:

Even though every attempt is made to ensure this information is complete and accurate, it is impossible to account for all possible circumstances or situations. Please consult with a qualified auto technician before attempting to perform any work you are not qualified to do. Automobiles can be hazardous to work on; be sure to take all necessary safety precautions. Failure to do so may result in property damage or personal injury. Certain motor vehicle standards and performance requirements may apply to your motor vehicle (such as Federal Motor Vehicle Safety Standards by the National Highway Traffic Safety Administration). Be sure that your work is performed in accordance with such standards and that you do not disable any motor vehicle safety feature.