






OFFICE: Unit No.505, 5/F., Sunbeam Center 27 Shing
Yip Street, Kwun Tong, Kowloon, Hong Kong
TEL: (852) 2389 1681 **FAX:** (852) 2763 9851

FACTORY: 2 JinYe Industrial Park, DaPing Village, GuanLan Town,
LongHua Zone, Shenzhen, China
TEL: (86-755) 28131750
FAX: (86-755) 28130128

Corrective Action Plan

Doc NO: QR-18-01-08 Version: A

To:	Amazon	From:	Master Hill
Attn:	Devendra	Date:	Nov.02, 2022
C. C:		Page:	Total 2 pages

产品编号 ASIN	B01418UEGY			Manufacturing No. 制造单号	Unknown	
产品规格 SPEC	Amazon Basics High-Speed Mini-HDMI to HDMI Cable - 1.8 m / 6 Feet (Latest Standard)					
Defect Qty 不良数量	Unknown	Delivery Qty 出货数量	Unknown	Delivery Date 出货日期	Unknown	
Step I Built Team 组成团队	Team Sponsor	Leo	Members 团队成员	Production 生产	Fu weiping	
				Engineering 工程	Stanley	
				Sales 业务	Murphy Wu, Claudia Chang	
				Quality 品质	Leo, Kenny	
Step II Problem Description 问题描述	Not working/faulty -The cable is not compatible with our device					
Step III Containment Actions 围堵措施	To enhance functional testing during production	Responsible Dept. 责任部门	Person in charge 负责人	Time 完成时间		
		Quality 品管部	Jiazhiqiang	2022-10-30		
Step IV Potential Root Causes 原因分析	<p>1、 It is a conventional HDMI and mini HDMI type plug. Only can use for the device port HDMI and</p> <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">  Micro HDMI </div> <div style="text-align: center;">  Mini HDMI </div> <div style="text-align: center;">  标准 HDMI </div> </div> <p>mini HDMI type interface,</p> <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">  Micro USB </div> <div style="text-align: center;">  Mini HDMI </div> </div> <p>2、 It is recommended to avoid excessive bending and pulling during the use of the product, so it will be connected to work smoothly.</p>					
Step V Immediate Corrective Actions 矫正措施	It is in standard requirement			Responsible Dept. 责任部门	Person in charge 确认人	Time 确认时间
			Engineering 工程 Quality 品管 Sales 业务	Stanley Leo Murphy	2022-10-30	
Step VI	1、 To ensure the output and receiving ports of the			Responsible Dept. 责任部门	Person in charge	Time 确认时间



OFFICE: Unit No.505, 5/F., Sunbeam Center 27 Shing
 Yip Street, Kwun Tong, Kowloon, Hong Kong
TEL: (852) 2389 1681 **FAX:** (852) 2763 9851

FACTORY: 2 JinYe Industrial Park, DaPing Village, GuanLan Town,
 LongHua Zone, Shenzhen, China
TEL: (86-755) 28131750
FAX: (86-755) 28130128

Corrective Action Plan

Doc NO: QR-18-01-08 Version: A

Preventative Actions 预防措施	equipment used at both ends can be matched for use.					确认人	
	2. It is recommended to avoid excessive bending and pulling during the use of the product, so it will be connected to work smoothly.				Production 生产 Quality 品管 Engineering 工程	Fu weiping Leo Stanley	2022-10-30
Approval 核准	Leo		Review 审核	Leo		Undertaker 承办	Kenny
StepVII Result Confirmation 效果确认	Record 确认记录	Date 确认日期	Q, TY 数量	Sheet No. 单据号码	Actions Approval 矫正预防措施效果确认		In charge of 确认人
	1st						
	2nd						
	3rd						
StepVIII Close Case 结案	<input type="checkbox"/> YES--DATE: / / (YYYY/MM/DD) 是- 日期: (年/月/日)			<input type="checkbox"/> Re-preparing corrective and preventive measures after three traces if the corrective actions have not improved 三次追踪仍未改善则重拟矫正预防措施			