

# Calibration Setting Instruction

Apply for KitchenTour Kitchen Scale

Model:EG5001-500g

prep work

1. kitchen scale
2. 2\*aaa batteries
3. 2 weights (200g,500g each one)



## Step 1

Turn on and Quickly click the "M" key 3 times in a row  
Long Press the third time until "500.00g" appear



## Step 2

Place the 200g weight on it when "200.00g" displayed



## Step 3

Place the 500g weight on it when "500.00g" displayed



## Step 4

When "PASS" is displayed , the calibration process is done.

For video guidance or any other questions please contact the after-sales email address:  
support@kitchentour.us