


Automatic Shutdown Time Setting and Calibration Setting Instruction

Apply for KitchenTour Coffee Scale
Model: EK6002

Prep work:


1. coffee scale
2. 3*aaa batteries
3. 3 weights (500g,1000g,2000g each one)

STEP 1.




Press four buttons (on/off, start, unit, tare) at the same time in the off state. Release until CAL appears.

STEP 2.




The default "auto shutdown time" appears on the screen is 240s. You can press "Tare" decide the time you want to shut down automatically, there are 0, 60, 120, 180, 240 to choose from.



After selecting the automatic shutdown time, press the "UNIT" button to go to the step 3.


If you only want to change the shutdown time, you also need to run all the 6 steps to complete the procedure.

STEP 3.



After 3000.0g (3000g) appears, press "Unit" to step 4.

STEP 4.




After a random number (three digits) appears, continue pressing "Start" to step 5.

STEP 5.



When CAL appears, you don't need to press any button, it will jump directly to step 6.

STEP 6.



Follow the on-screen prompts to place the weights in sequence to complete the calibration process.

Ready to use as soon as the calibration process is completed.

Warim Tip:

1. The above 6-step process can not be quitted when in the process, if the setting error, you can press "On/Off" for seconds or directly pull out the battery to re-start.
2. After reinserting the battery, the scale will return to deefault setting including automatic shutdown time and re-calibration.
3. If you just set the auto-off time (without recalibration), you still need to complete the above 6-step process. So, if you simply set the auto-off time, you also need to prepare these weights (500g, 1000g, 2000g).