



Assembly Instructions for C-frame

www.factorydirectwholesales.com

HK-CC79



WARNING:

Frame load limit 300 pounds.

The fram is not intended to be a swing set.

Failure to adhere could result in injury.

CARE AND MAINTENANCE:

-inspect the welded joints around the foot brackets periodically.

-check that no parts have rusted through, especially on any welded area.

using a commercclally available rust Inhibltor will prblong the life

of your frame (read manufactures instructions)

If any parts are missing,broken,damaged or worn,stop using this product until repairs are made and factory replacement parts are installed.

You may obtain replacement parts by calling 706-520-1087