


Pocket Kitchen Scale

INSTRUCTIONS



Thank you for purchasing OUR pocket kitchen scale. With normal care and proper treatment, this scale will provide years of reliable service.

Maintenance and Care

1. Avoid exposure to extreme heat or cold. Also avoid any kind of moisture. Always allow your scale to acclimate to normal room temperature before use.
2. Keep your scale in a clean and dry environment may have an adverse effect on the accuracy and reliability of the scale.
3. Handle the scale with care. Gently apply all items to be weighed on the tray top. Although this scale is designed to be quite durable, avoid rough treatment, as this may permanently damage the internal parts. Always avoid shaking and dropping. This is a precision instrument and should be handled with extreme care.

Specifications

- Model:KA8, Capacity: 500g, Accuracy: 0.01g
- Units: g, oz, ozt, dwt, ct, gn
- Key function: ON/OFF, UNIT, PCS, TARE
- Display: LCD display with blue backlight
- Auto off: 180 seconds of inactivity
- Power: 2 AAA batteries
- Operation Tem: 10 to 30 deg C

Operation

1. Place the scale on a leveled surface & press "ON/OFF" key to turn on the scale or power it off.
2. Wait until the LCD display shows zero, then press "UNIT" key to choose the weighing unit.
3. Place the item to be weighed on the surface and wait until the reading is stable.

Tare Function

1. Turn on the scale as described above.

2. Place the "tare item" on the platform. Press "TARE" key and wait until the LCD displays zero.
3. Scale can now be used for weighing. Add the "net-weight-item"

Counting Function

1. Place the scale on a leveled surface & power on it.
2. Sampling: Prepare a sample quantity (25, 50, 70 or 100 pcs) of the item you want to count. Put the item on the platform, press and hold the "PCS" key until the scale shows "25", "50", "70", or "100". Press the "UNIT" key to switch the above figures to match the quantity of the items on the platform. Press the "PCS" again and display will show "pcs" in the lower left hand corner. Sampling is completed.
3. Put the items you want to count on the platform and display will show the quantity of these items.

Warning

1. "Lo": Low voltage. Please replace the batteries.
2. "O-Ld": Over load. Please remove item quickly to protect the scale.

Package Includes:

- 1× Digital pocket scale
- 2× Platform cover
- 2× AAA batteries
- 1× User Manual